## **EAST Search History**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	17775	(force ) near3 (sens\$4 detect\$4 transducer measur\$4 gauge gage ).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/25 16:47
L2	143	1 and (washer ).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/25 16:52
L3	54	2 and (electrical\$4).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/25 16:43
L4	19	3 and (head )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/25 16:43
L5	13	4 and (screw )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/25 16:46
L6	123610	(screw ).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/25 16:52
L7	24232	6 and (head ).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/25 16:46
L8	6213	7 and (nut bolt ).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/25 16:46
L9	1325	8 and (force ).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/25 16:52

10/25/06 4:55:25 PM Page 1

## **EAST Search History**

L10	213	9 and (sens\$4 detect\$4 transducer	US-PGPUB;	OR	ON	2006/10/25 16:47
		measur\$4 gauge gage ).clm.	USPAT; USOCR; EPO; JPO; DERWENT			
L11	25	10 and (washer ).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/25 16:52
L12	1	("2003/0039527").URPN.	USPAT	OR	ON	2006/10/25 16:49
L13	568	73/761.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/25 16:52
L14	35	13 and (washer ).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/25 16:52
L15	4	14 and (screw ).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/25 16:52
L16	2	15 and (force )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/10/25 16:53

10/25/06 4:55:25 PM Page 2